	,			DOCUMENT	MODIFICA	TION REQ	UEST (DMR)	PAGE 1 of		
Refer to 1-A01-PPG-001 for Processing Instructions. Printor Type All Information (Except Signatures).						5/24/95	DMR No.	95-DMR-000 7 อ	25 5,95	
ting	g Docume	nt Number/Re	wision MRG-1.0	Rev 1		3. New Document Num	mber or Document Number if it is	to be changed with this R	evision	
M83-ER-OPS-EMRG-1.0 Rev 1 4. Originator's Name/Phone/Pager/Location K. Anderson 6979 / 5142 / Bldg 080						5. Document Title Environmental Management Radiological Guidelines for Organization and Responsibilities				
6. Document Type					-					
Oth 8. Item	9. Page	10. Step		11000 - 11000-	11. Proposed N		,			
1	6	3.3	Add	new sentence to re	ad: "Oversees	activities of H	lealth and Safety Mo	nitors."		
2	6	3.5	5 Add				fety Monitors are trai		edures	
			1	controlling the monitoring activitees performed."						
3	6	3.7	Add new section to read: 3.6 Environmental Restoration Subcontractor Health And Safety Monitor							
			[cal and chemical co			
		1	i	Conducts presite su	•	-				
				Performs personne	I monitoring at	step-off pad c	or contamination redu	uction corridor.		
				Notifies subcontract and chemical expos			alist when action leve	als for radiologic	;al	
12. Justifi	ication (R	eason for Mo	dification, EJO #,					<u> </u>		
							REV	MENT CLASSIFICAT VIEW WAIVER PER SIFICATION OPFIC	}	
				n, list concurring disciplines in Blasigns in Block 14, and dates in B		in Blocks 14 and 15. If r	modification is for any type of cha	inge or a cancellation, org	anizations	
13. Organi	ization	14. Print, Sign	n (if applicable)						15. Date (if applicable)	
EOM		KD An	derson <	Kut D. C.					6/1/95	
& MD	RS	NA								
RE		NA								
IH&S		NA			X	\			1.1-10,-	
CKH		<u> </u>	NKER (SRHUGHES) AT P Augles						4/5/75	
					}					
	نالنر		VING- RE	sucos Al	<u></u>		 -			
	Brous:	ervisor (print/s	VINO /S	roussay	6-1-95					
17. Assigned SME/Phone/Page//Location D. Anderson/6979/5142/08				.0	18. Cost Center 0248	19. Charge Number 986538	20. Requested Completion 06/02/95	n Date 21. Effective Date 6 - 9	195	

6/1/95

RF-47940 (5/93). RCC. For Clist. 6/5/95

23.ORC Review

celerated Review?
Yes No No

24. Responsible Manager (print, sign, date)
KD Anderson

REVIEWED FOR CLASSIFICATION / UCNI

DATE

20. Requested Completion Date 21. Effective Date 06/02/95 6-9

DMR (continuation sheet)

Page 2 of 2

Refer to 1-A01-PPG-001 for Processing Instructions.

Printor Type All Information (Except Signatures).

26. DMR No. 95-DMR-000 726 65 95

2. or 3. Document Number/Revision 5. Document Title Environmental Management Radiological Guidelines for Organization and Responsibilities 4-M83-ER-OPS-EMRG-1.0 Rev 1 9. Page | 10. Step 11. Proposed Modifications 7 4.[1] Change: Minimum qualifications to [A] Minimum qualifications...... Add a 2nd bullet for . Experience: Minimum of 2 years of "hands-on" experience in Radiological Protection and Worker Health and Safety Programs. This includes the identification, evaluation, and control of occupational health and safety hazards. Add [B] Minimum qualifications for personnel selected to perform Subcontractor Health and Safety Monitor functions are: Education: High school diploma Training: Documented training to procedures......

ification (Reason for Modification)

95 DIAR-COOPILE

3.3 Environmental Restoration Subcontractor HSS (continued)

Verifies performance testing of Rocky Flats and subcontractor-owned instruments in accordance with the manufacturer's recommendations.

Maintains an Instrumentation Field Log Book that contains documentation for the specific equipment used at the work site.

Reports all radiological concerns or deficiencies to the ERRE.

Obtains approval from Oral Review Board prior to performing Subcontractor HSS duties.

Oversees activities of Health and Safety Monitors.

3.4 Environmental Restoration Subcontractor Project Manager

Nominates Site Safety Officers (SSOs) and Subcontractor HSSs for the ERRE's approval to ensure that all qualifications for the positions have been fulfilled.

Supervises Subcontractor HSSs in the performance of their responsibilities.

Ensures compliance with the Health and Safety Practices Manual.

3.5 Environmental Restoration Subcontractor Site Safety Officer (SSO)

Supervises Subcontractor HSSs in the performance of their responsibilities.

Reviews, approves and maintains completed survey reports and forms.

Notifies the ERRE and the Industrial Hygienist of areas that require access controls or action level.

Ensures Health and Safety Monitors are trained to the procedures controlling the monitoring activities performed.

3.6 Environmental Restoration Subcontractor Health and Safety Monitor

Conducts precautionary monitoring for radiological and chemical contaminants.

Conducts presite surveys for nonoccupational exposure concerns.

Performs personnel monitoring at step-off pad or contamination reduction corridor.

Notifies subcontractor Health and Safety Specialist when action levels for radiological and chemical exposure are met or exceeded.

ROCKY FLATS PLANT EM RADIOLOGICAL GUIDELINES

Manual No.: Procedure No.:

Page: Effective Date: 3-21000-OPS-EMRG Table of Contents, Rev 10

1 of 2 06/09/95

Organization: Environmental Management

TABLE OF CONTENTS

	Title	Rev. No.	Effective <u>Date</u>
4-M83-ER-OPS-EMRG-1.0	Environmental Management Radiological Guidelines for Organization and Responsibilities	1	02/09/95
	•95-DMR-000726		06/09/95
EMRG 1.1	Gama Radiation Surveys	0	12/06/91
EMRG 1.2	Beta RadiationSurveys	0	12/06/91
•EMRG 1.3	Posting of Radiation Protection Requirements	1	06/09/95
EMRG 2.1	Personnel Contamination Monitoring	0	12/06/91
EMRG 2.2	Possible Inhalation Exposure	0	12/06/91
EMRG 2.3	Wounds and Skin Contamination	0	12/06/91
3-P11-ER-OPS-EMRG-3.1	Performance of Surface Contamination Surveys	1	05/26/95
3-B96-ER-OPS-EMRG-03.02	Survey Requirements for Conditional and Unrestricted Use	1	05/31/95
EMRG 3.5	Handling of Contaminated Dosimetry/Security Badges	0	12/06/91
EMRG 6.1	Performance Test and Operational Checks for Ludlum Model 12-A, Model 12, and Model 31 Survey Instruments	0	12/06/91
EMRG 6.3	Performance Checking and Operation of the Eberline SAC-4 Alpha-Scintillation Smear Counting Instrumentation	0	12/06/91
EMRG 6.4	Performance Testing and Operation of the Eberline BC-4 Beta Smear Counting Instrumentation	0	12/06/91

ROCKY FLATS PLANT EM RADIOLOGICAL GUIDELINES

Manual No.: Procedure No.: 3-21000-OPS-EMRG Table of Contents, Rev 10

Page:

Effective Date:

2 of 2 06/09/95

Organization:

Environmental Management

	<u>Title</u>	Rev. No.	Effective <u>Date</u>
EMRG 6.5	Use of the Bicron Frisk-Tech with the A-100 and B-50 Detectors	0	12/06/91
EMRG 6.6	Use of the Bicron Fidler (Field Instrument for the Detection of Low-EnergyRadiation)	0	12/06/91
	94-DMR-ERM-0012		01/25/94
4-P12-ER-OPS-EMRG-6.7	Performance Checking and Operation of Ludlum Smear Counting Instruments	0	04/07/95
•EMRG 9.1	Respiratory Protection Requirements and Posting	1	06/09/95
EMRG 10.1	Radiological Deficiency Reporting Program	0	12/06/91

4. TRAINING

Environmental Restoration Program Division Project Manager

- [1] Ensure that subcontractor HSSs are trained and qualified to perform the duties, tasks, and responsibilities described in this procedure.
 - [A] Minimum qualifications for personnel selected to perform Subcontractor Health and Safety Monitor functions are:
 - . Education: High school diploma
 - Experience: Minimum of 2 years of "hands-on" experience in Radiological Protection and Worker Health and Safety Programs. This includes the identification, evaluation, and control of occupational health and safety hazards
 - Training: Documented training to procedures that control monitoring activities defined in Section 3.6.
 - [B] Minimum qualifications for personnel selected to perform Subcontractor Health & Safety Monitor functions are:
 - . Education: High school diploma
 - Training: Documented training to procedures that control monitoring activities defined in Section 3.6.
- [2] Ensure that all core and Environmental Restoration Program Division specific training has been completed and documented, and that copies of all documentation have been forwarded to the Environmental Restoration Program Division training files.